

Fehlermatrix Sulden Pfarrkirche.xlsx

Werk	Register	C	C#	D	D#	E	F	F#	G	G#	A	B	H	c ⁰	c# ⁰	d ⁰	d# ⁰	e ⁰	f ⁰	f# ⁰	g ⁰	g# ⁰	a ⁰	b ⁰	h ⁰	c ¹	c# ¹	d ¹				
Pedal	Subbass 16'					V		V																								
	Flötenbass 16'			I																												
	Cello 8'																															
I - Hauptwerk	Bordun 16'											X											R									
	Principal 8'	A					R					X			R			R														
	Gedeckt 8'									R		X																				
	Salizional 8'											X			R																	
	Flauto amabile 8'											X		A						A	A	A	A	A	A	A						
	Oktav 4'			R				R				X																				
	Gemshorn 4'											X																				
	Mixtur 2 2/3'											X																				
II - Schwellwerk	Geigenprinzipal 8'	AT				T														A												
	Oboe 8'																															
	Viola 8'								T		T				T				T							S		A				
	Rohrflöte 8'														A				A									S				
	Äoline 8'										A																					
	Vox Cölestis 8'																				T					T	T					
	Traversflöte 4'																															
Pedal- & Manualkompass																																

Sonstige Fehler

- Piston "pp an" scheinbar ohne Funktion (ursprüngl. Registerauswahl unbekannt)
- Koppel "Super II" löst nach kurzer Wartezeit konstanten Spielwind auf II-f#¹ aus
- Crescendo-Pedal löst in 100%-Stellung nach kurzer Wartezeit stotternden bis konstanten Spielwind auf II-f#¹ aus

